

MCV SERIES

PRODUCT	PROBLEM	SERVICE BULLETIN #	COLOR
MA 56, 57, 70, 91, 93 When used w/remote control	Audio feed through problem on transmit with remote units.	78-0147	W
All current models	Available service information.	78-0149	W
E & R Tone Wideband Receivers	Filters	78-0151	G
MA 126, MA 79 Handset used with MCH 40, MCU 30	Bassey Transmit Audio	79-0158	W
MA 305 Helical Preselectors	Revised MA 305 Service Manual.	79-0159	W
412 and MCB/CBS Base Stations	SCR overvoltage circuit failure in P1412.	79-0161	W
MA 114, 115, 146, 164 Mic Hangup	Intermittent CTCSS Operation.	79-0163	W
MA 116 Board 504-046 REV. A & B	Changes necessary when using in Repeater with tone control board.	80-168	B
MA 147 Board 1700-5416-000 Rev. C	False Decoding	80-169	W
MA 177 Imp. Adapter	Hum on transmit and receive audio.	80-172	W
P1412 Power Supply	Definition of circuit changes. Revisions A, B, C.	80-177	W
MA-116 P.C. Board 504-046 REV. "C" only	Low receive sensitivity after transmitter is keyed.	80-178	W
P1412 Power Supply	Definition of circuit changes. Revision D.	80-188	W
MA 318, 178	Transmitter keys when handset is lifted.	81-192	W

OPTIONS AND TONES

W = White B = Blue
G = Green Y = Yellow
P = Pink

PRODUCT	PROBLEM	SERVICE BULLETIN #	COLOR
MA 319	Remote base with tone will not go into monitor mode if used with local telephone.	81-193	W
P1412 Rev. C and D	High line voltage causes Power Supply SCR to fire and shut off output.	81-195	W
MA 325	Installation instructions for units other than the MCB.	81-203	W
MA 301, 131	Compatibility of MA 301 and MA 131.	81-208	W
MA 186, 314, 315	RF causing DTMF tones (MA 186, MA 315) 2805 tone (MA 314) not to be transmitted or distorted when transmitted.	81-212	W
MA 325	Will not fit into XLH series radios due to short wire lengths. Also MA 325 will not fit into MCU series mobile radios due to speaker interference.	81-213	W
MA 164, 166, 300	Addendum to Service Manual.	81-221	W
MA 325E	Reference Service Bulletin 81-203 Figure 2.	81-222	W
MA 187	Addendum - hook up information for installing in the TRPH radio.	82-228	W
MA 317	Modification of the MCA611A Rev H and lower necessary for MA 317 installation.	82-232	W
MA 355	Will not stop on active channel when used with CTCSS decoder.	82-233	W



OPTIONS AND TONES

W = White B = Blue
G = Green Y = Yellow
P = Pink

PRODUCT	PROBLEM	SERVICE BULLETIN #	COLOR
MA 337, 344	Mounting positions of options in XLU series radios.	82-234	W
MA 329	Revision on instruction sheet.	82-235	W
MA 325	Addendum: RAP200 & SAI800 instructions.	82-238	W
MA 325	Interference - Fit when mounting option board to a Rev. "N" control board.	82-247	W
BAH 100	Service Manual Errata	82-251	W
ACU45A/AASCU45A	Changes of parts of new models. Models in field not affected.	82-253	B
MA 337	The MA 337 decodes other ID codes along with the correct ID code.	82-261	W
MA 355	Scanner continues to scan when Tx. is keyed.	82-264	W
MA 357H	Mobile Amp/Chg. tuning procedure.	82-267	W
MA 332 (Service Manual)	Replace page.	82-269	W
MA 330	Excessive base tone in transmit audio.	82-270	W
MA 312	Motorboating sound in audio when in intercom or busy modes.	82-273	W
MA 312	Service Manual Changes	82-274	W
MA 337/338	Excess squelch noise in radio failure to decode at low temp.	82-277	W
MA 312/313	Command or display data not correct. Production & Service Manual Changes.	82-280	W
MA 330/331	Service Manual Changes	82-281	W
MA 337/338	Service Manual Changes	82-283	W
MA 187	Installation Instructions added.	82-285	W



W = White B = Blue
G = Green Y = Yellow
P = Pink

OPTIONS AND TONES

PRODUCT	PROBLEM	SERVICE BULLETIN #	COLOR
MA199 A/B/C/D	Service Manual errata.	82-278	W
MA164/165/166	Insufficient CTCSS tone deviation when used in MCE20.	83-290	P
MA332	Service Manual errata.	83-294	W
MA337	Manual correction	83-295	W
MA332	Squelch tail.	83-296	W
MA337	Installation in TRH202.	83-310	W
MA301	Updating interface circuits Rev. "H".	83-306	W
MA187	Programmable CTCSS encoder/decoder addendum.	83-311	W
MA186/315/330	DTMF twist adjustment.	83-318	W
MA322	Erratic operation with low voltages.	83-323	W
MA193 (TTS Decode) & MA367	Service Manual errata.	83-324	W
MA131	Parts availability.	84-330	W
MA303	Service Manual changes.	84-331	W
MA301	Unit alerts radio erroneously when car is started.	84-334	W
BAH100	Service Manual changes.	84-337	W
MA164/165	Service Manual changes.	84-340	W

